

Digital Welding Gage Cat #18



Abilities:

- Holds either the zero setting or measured value at any position for differential measurements.
- Has a serial output to interface with a computer or printer to process data.
- Automatically turns on by moving the main scale or by pressing ON/OFF key.
- Automatically turns off after 4 minutes of inactivity ... conserving battery power.

Features:

Measures Butt Weld Reinforcement Measures Throat LCD Display IN / MM Switch
Slider Clamp Screw Output Connector Hold Switch ON / OFF Switch

Model No.	Range (usage 1)	Range (usage 2)	Resolution
1110-301	10mm/0.4"	20mm/0.8"	0.01mm/0.0005"



