## ND-4000B



120 VAC hard wired or plug-in economical Area Monitor Non-adjustable trip point at 2 mR/hr Will activate and 120 VAC device such as lights and sirens Two 5 amp 120 VAC remote alarm outlets One AC power On/Off green indicator and one red alarm trip indicator Operating Temperature: -20 to 50 °C (-4 to 122 °F), Humidity: Non-Condensing 95% NEMA 3R steel case: 8" W x 9" H x 5" D 6 pounds Halogen quenched energy compensated GM tube, Gamma and X-Ray from 60-2000 KeV +/- 20%





EQUIPAMENTOS PARA ENSAIOS E INSPEÇÃO